


LOCATION OF THE SEALS (EXTERIOR AND / OR INTERIOR) MUST BE DETERMINED BY THE PROJECTS DESIGNER. FAILURE TO DETERMINE AND APPLY THE PROJECT'S VAPOR SEAL(S) MAY RESULT IN CONDENSATION PROBLEMS AND WILL NOT BE THE RESPONSIBILITY OF TRUECORE.



NBTC = NOT BY TRUECORE



PANEL SIDE JOINT

| | | |
|------------------|--------------------|--------------|
| DRAWN BY: DBN | DATE: 9-23-2019 | DRAWING NO.: |
| | | JT1 |